

207 Paint door
208 Paint door
216 Paint door
PAINT 2nd floor East Side stair access and elevator door



Match paint next to 202



Paint pass-thru between 222 and 221



Cracked Light west side of 313 (courtyard side)



3rd floor near 312 courtyard side, match paint near downspout and windowsill.



Loose tile near p10 courtside



Loose tile near P8 courtyard side.



Loose tile near p7 courtyard side



Paint 3rd floor northwest stairway door and elevator





**EMERGENCY
EXIT**

STAIRWAY

Paint corner of stairway near 101.... Maybe all of the stairway rails need attention.



Loose/cracked tiles between both 120 and 121 and the pool area. One area photographed here.



Paint Door 116



Paint elevator door 1st floor east



Paint Door 113



Paint Door 112



Match Paint outside 110



Paint Door 108



First floor northwest fix non-closing trash room door



Patch/match concrete at entrance



Oops plate in lobby



Lobby elevator paint (no picture)

Paint Door P9



Fix wall



